

Eventioneers Event Rental and Supplies

11171 Perry Highway

Wexford, PA 15090

(724) 766-6531

Popcorn Machine Instructions

- 1. Plug in machine and turn all switches to the “ON” position**
- 2. Allow to heat up for 3-4 minutes**
- 3. Empty butter/oil package into kettle and wait to melt**
- 4. Empty kernel package and close the lid**
- 5. As soon as you hear the kernels stop popping, empty kettle**
- 6. Repeat process as popcorn is needed**